



LIVER OF SULPHUR

No. 520-749

DIRECTIONS:

Mix with water until the mixture attains a deep yellow color. Water may be heated to hasten the process, but DO NOT BOIL. Stir until all of the Liver of Sulphur is dissolved. Immerse the clean metal piece until it begins to color or paint the solution onto the metal piece. When dipping, remove the piece periodically for inspection and continue to immerse until desired color is attained. Rinse in water and dry. Buff metal when dry to bring out the highlights.

CAUTION: *Keep out of reach of children. Avoid inhalation. Do not mix with acids. Do not subject Liver of Sulphur to elevated temperatures. Keep container tightly closed when not in use and away from oxidizing materials. Harmful if swallowed or absorbed through skin. Wear protective eyewear and gloves when handling.*

FIRST AID:

EXTERNAL - *Wash with soap and water after handling.*

INTERNAL - *If injected, immediately induce vomiting and consult a physician.*

EYES - *Wash with water and consult a physician.*

INHALATION - *Remove to fresh air. If not breathing, administer artificial respiration. If breathing is difficult, provide oxygen.*